


### A12T Temperature Humidity Meter




Specifications	Range	Best Accuracy
Model		<b>UNI-T A12T</b>
Temperature	Range	-10~50°C (14~122°F)
	Resolution	0.1 °C (0.1°F)
	Accuracy	±1 °C (±1.8°F)
External temperature probe	Range	-10~50°C (14~122°F)
	Resolution	0.1 °C (0.1°F)
	Accuracy	±1 °C (±1.8°F)
Humidity	Range	10~99%RH
	Resolution	1%RH
	Accuracy	±5%RH
<b>Features</b>		
LCD size		4.5"
Comfort classification		√
Sampling frequency		10s
Alarm clock		√
Time		√
Date		x
12/24 hours conversion		√
MAX/MIN		√
Battery		1*AAA
Certification		CE

#### 1. Structure description



1	MAX/MIN value key	2	Mode key
3	Adjustment key	4	External probe socket (A12T only)
5	QR-code	6	Wall-mount hole
7	Stand	8	Battery cover

#### 2. Display description



1	Alarm symbol
2	Temperature unit(°C)
3	Temperature symbol
4	Max value of temperature measured by inner sensor
5	Value of temperature measured by inner sensor
6	Min value of temperature measured by inner sensor
7	Symbol of temperature measured by inner sensor
8	Comfort level symbol
9	AM / PM